



Sterilization Assurance Service
Loma Linda University School of Dentistry
11175 Campus St., CSP A-1005, Loma Linda, CA 92350
Tel (909) 558-8176, Fax (909) 558-0307; sas@llu.edu

Dental Unit Waterline Testing Results

Office Name Andrey Eng, DDS
Address 20397 Yorba Linda Blvd.
Yorba Linda, CA 92886
E-mail engddsinc@gmail.com
Tel/Fax 714-779-2736 / 714-779-5739

Customer ID WT-0334
Receiving date 11/1/2019
Report date 11/7/2019
SAS staff initial OM

Notify the shipping to sas@llu.edu or (909) 558-8176, provide ID, Sample # & Tracking #.

Sample #	Location Room / Chair / Waterlines	SAS Laboratory only	
		Microbial Count (CFU/mL)	DUWL Testing Results
# 1	room 1 a/w syringe	0	Pass
# 2	room 1 handpiece tubing	0	Pass
# 3	room 2 a/w syringe	0	Pass
# 4	room 2 handpiece tubing	0	Pass
# 5	room 3 a/w syringe	20	Pass
# 6	room 3 piezo scaler	0	Pass
# 7	room 4 a/w syringe	10	Pass
# 8	room 4 piezo scaler	0	Pass
# 9	room 5 a/w syringe	0	Pass
# 10	piezo scaler	10	Pass
# 11	Control - C	10	Pass
	SAS Lab Blank	0	Pass

TMTC*: too numerous to count

The CDC recommends that coolant water used in non-surgical dental procedures meet EPA regulatory standards for drinking water, which is less than or equal to 500 colony forming units (CFU) of heterotrophic bacteria per milliliter of water.

We provide Dental Unit Waterline Testing and Sterilization Assurance Service to dental professionals

For assistance or reorder, please contact us at Loma Linda University, Sterilization Assurance Service

Tel: 909-558-8176, (909) 558-8069, fax: (909) 558-0307, e-mail sas@llu.edu.

Water Quality Certificate

Awarded to

Andrey Eng, DDS Inc
East Lake Advancing Dentistry

for maintaining dental unit water quality that
meets the requirement of American Dental Association (ADA)

Issued by:

Sterilization Assurance Service
Loma Linda University
School of Dentistry

Wu Zhang

Wu Zhang, Director



Valid through

February 1, 2020